



U.S. Department  
of Transportation

## United States Coast Guard



# LOCAL NOTICE TO MARINERS

## FEBRUARY WEEKLY SUPPLEMENT

NOTICE NUMBER 07/03  
18 February 2003

NIS watchstander, 24 hours a day at (703) 313-5900

**\*\* INTERNET ADDRESS \*\***  
**<http://www.navcen.uscg.gov/lnm/d14/>**

ISSUED BY: Commander, Fourteenth Coast Guard District (oan)  
PJKK Federal Building, Room 9-236  
300 Ala Moana Boulevard  
Honolulu, HI 96850-4982  
Telephone: (808) 541-2317 Nights: (808) 541-2500 Fax: (808) 541-2309  
**Email: [cbearden@d14.uscg.mil](mailto:cbearden@d14.uscg.mil)**

Navigation information having been ⇒ CCGD14 (D14) BNMs: 072-03 to 080-03  
of immediate concern to the Mariner, ⇒ COGARD MARIANAS SECTION (MARSEC) BNMs: 031-03 to 039-03  
and promulgated by the following  
broadcasts, has been incorporated in  
this notice when still significant:

NOTES: (1) Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution.  
(2) The Local Notice to Mariners is published in its entirety once a month. The Monthly Edition should be retained as a reference for subsequently issued Weekly Supplements. The Weekly Supplements will be published in intervening weeks and will contain only new information with the exception of DISCREPANCIES-DISCREPANCIES CORRECTED section that is an accurate list maintained each week.

REFERENCES: Light List, Vol. VI, Pacific Coast and Pacific Islands, 2002 Edition (COMDTPUB P16502.6).  
U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, and Hawaii (34<sup>th</sup> Edition).

**REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT**

## **I. SPECIAL NOTICES**

### **LOCAL NOTICE TO MARINERS ON THE INTERNET**

The Fourteenth District Local Notice to Mariners (LNM) is available on the World Wide Web at <http://www.navcen.uscg.gov/lnm/d14/>. Customers with Internet access are encouraged to take advantage of this service. The Internet delivers faster information, gives multiple copy customers the ability to print needed amounts, and provides access to archived LNM information as far back as 1995.

### **PUBLICATIONS – U.S. COAST GUARD – LIGHT LIST VI, PACIFIC COAST AND PACIFIC ISLANDS, 2003 EDITION – ONLINE**

The 2003 U.S. Coast Guard Light List Volume VI (GPO Stock Number: 050-012-00437-4/ISBN: 0-16-067669-X) is now available on the USCG Navigation Center Internet site (<http://www.navcen.uscg.gov/pubs/LightLists/LightLists.htm>). Hard copy edition will be available in April 2003 from the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402. For pricing, ordering information, and availability, please contact the Superintendent of Documents by calling 202-512-1800.

### **MARIANA ISLANDS - GUAM - APR A HARBOR**

The U.S. Coast Guard Captain of the Port Guam and Commander Naval Forces Marianas are enforcing the Naval Vessel Protection Zone for all U.S. Naval vessels transiting through or moored within Apra Harbor, Guam. All vessels within 500 yards of a U.S. Naval vessel must operate at a minimum speed necessary to maintain a safe course and must proceed as directed by an official patrol. Vessels are not allowed within 100 yards of a U.S. Naval vessel, unless authorized by the official patrol. Vessels requesting to pass within 100 yards of a U.S. Naval vessel must contact the official patrol on VHF-FM Channel 16.

### **HAWAIIAN ISLANDS – KAHOO LAWE – ORDNANCE DETONATIONS**

Planned ordnance detonations will be conducted around the island of Kahoolawe in an area bound by the following coordinates: 20-37-30N 156-32-48W, 20-34-48N 156-30-24W, 20-28-54N 156-30-24W, 20-28-06N 156-41-48W, 20-30-30N 156-44-12W, 20-33-12N 156-44-30W, 20-37-30N 156-36-24W, thence to the point of origin, effective 0800W-1700W on the following dates: 17-22 FEB 03, 24 FEB - 01 MAR 03, 03-08 MAR 03, 10-15 MAR 03, 17-22 MAR 03, 24-29 MAR 03, 31 MAR - 05 APR 03. In the interest of safety, all vessels are requested to remain clear of the area.

### **HI ISLANDS - OAHU - MAMALA BAY – OBSTRUCTION TO NAVIGATION**

Commencing on or about Wednesday, 19 February 2003, Healy Tibbitts Builders, Inc. will begin work on the offshore section of the Ft. Kamehameha Outfall with a second barge. The area affected by this work is immediately offshore and to the east side of the entrance channel to Pearl Harbor beginning at approximately 150 ft offshore of Pearl Harbor Channel Buoy R "2". The work area will extend to approximately 1,300 feet offshore of Buoy R"2", parallel and to the east side of the entrance channel and then along the 25 fathom contour towards the southeast for approximately 1,000 feet. Work will be performed from barge WEEKS 544 (160 feet by 50feet). Barge will be on location for approximately 3 weeks. Barge will be secured on a 6-point anchor mooring system. Anchors will be marked with lighted yellow crown buoys. The call sign for Barge WEEKS 544 is WCT8969. Barge will monitor VHF-FM CH 16 and 69 for all concerned traffic. Mariners are requested to use extreme caution while transiting the work area. Point of contact is Lou Neron at (808) 422-8587.

### **HI ISLANDS - OAHU - MAMALA BAY – RESTRICTED AREA**

Effective immediately naval station Pearl Harbor has established a restricted area 1500 yards either side of the Pearl Harbor entrance channel. No fishing, diving, wading, anchoring or loitering is authorized without the permission of Commanding Officer, Naval Station Pearl Harbor Hawaii (NAVSTA PH) in the area bounded by the following coordinates: 21-18-57N 157-58-57W; 21-17-33N 157-58-09W; 21-18-12N 157-56-45W. Vessels authorized to transit from Hickam Harbor marina to sea and return must transit in an expeditious manner with no loitering during the transit. Questions should be addressed to NAVSTA PH Security Operations personnel at (808) 474-7679.

### **HAWAIIAN ISLANDS – OAHU – MAUNALUA BAY – HAWAII KAI – DREDGING OPERATIONS**

Maintenance dredging will be performed at the small boat ramps in Maunalua Bay, Hawaii Kai, Oahu commencing 03 March 2003. Operations will continue for approximately 3 days. All Mariners are advised to use caution when transiting the area. Point of contact is Mr. Don Ford, (808) 438-9258.

## **II. DISCREPANCIES - DISCREPANCIES CORRECTED**

### **Abbreviations normally used in the Local Notice to Mariners**

BNM – Broadcast Notice to Mariners  
LNM - Local Notice to Mariners  
TUB – Temporary Unlighted Buoy  
TLT – Temporary Light  
IMPCHA – Improper Characteristics  
REDINT – Reduced Intensity

TRLB – Temporarily Replaced by Lighted Buoy  
TRUB – Temporarily Replaced by Unlighted Buoy  
TLB – Temporary Lighted Buoy  
TDBN – Temporary Daybeacon  
INOP – Inoperative

### **DISCREPANCIES: Federal Aids:**

**Shaded text denotes new discrepancy since last LNM.**

LLNR	Name of Aid	Status	Chart Affected (Largest Scale)	BNM Reference	LNM Reference
28008	NOAA Data Buoy 51001	REMOVED	19016	012-03	02A/03
28320	Kawaihae Harbor South Breakwater Light 8	LIGHT EXTINGUISHED / MISSING DAYBOARDS	19330	074-03	07/03
29175	Honolulu Harbor Entrance Lighted Buoy H	STROBE EXTINGUISHED	19367	070-03	07/03
29710	Haleiwa Harbor Entrance Lighted Buoy 2	OFF STATION	19357	006-03	02/03
29720	Haleiwa Harbor Buoy 3	OFF STATION	19357	007-03	02/03
29725	Haleiwa Harbor Buoy 4	MISSING	19357	005-03	02/03
29735	Kilauea Point Light	REDINT	19385	079-03	07/03

## II. DISCREPANCIES - DISCREPANCIES CORRECTED (Cont.)

### DISCREPANCIES: Federal Aids:

Shaded text denotes new discrepancy since last LNM.

LLNR	Name of Aid	Status	Chart Affected (Largest Scale)	BNM Reference	LNM Reference
30085	Johnston Atoll Channel Range Front Light	REPORTED EXTINGUISHED	83637	081-03	07/03
30350	Kwajalein-Roi Highway Channel Buoy 4	OFF STATION	81715		02/03
30710	Glass Breakwater Light	MISSING DAYBOARDS	81054	018-03	50/02
30910	Tanapag Harbor Channel Buoy 8	OFF STATION	81076	012-03	01/03
30940	Tinian Harbor Channel Light 5	DESTROYED	81071	022-03	52/02
	Rota CG Mooring Buoy	MISSING	81063		51/02

### DISCREPANCIES: Private Aids:

LLNR	Name of Aid	Status	Chart Affected (Largest Scale)	BNM Reference	LNM Reference
28411.4	Kihe Boat Ramp Daybeacon 4	MISSING	None	043-03	04/03
29110	Ala Wai Boat Harbor Channel Daybeacon 3	TRUB	19369		33/00
29110	Ala Wai Boat Harbor Channel Daybeacon 3	TRUB REPORTED MISSING	19369	229-02	48/02
29115	Ala Wai Boat Harbor Channel Daybeacon 4	TRUB	19369		10/01
29670	Pokai Bay Breakwater Light 2	REDINT	19357		39/02
30811.3	Agat Small Boat Harbor Light 3	REPORTED MISSING	81048	084-02	28/02
30811.6	Agat Small Boat Harbor Daybeacon 6	REPORTED MISSING	81048	084-02	28/02
30811.8	Agat Small Boat Harbor Daybeacon 8	REPORTED MISSING	81048	084-02	28/02
30811.9	Agat Small Boat Harbor Daybeacon 9	REPORTED MISSING	81048	084-02	28/02

### DISCREPANCIES: FAD Buoys:

Name of FAD	Assigned Location	Assigned Position	Status	Chart Affected (Largest Scale)	LNM Reference
G	Pepeekeo - Hawaii	19-50-42N 154-53-18W	REPORTED MISSING	19320	03/03
V	Makua, Oahu	21-32-18N 158-18-48W	REPORTED MISSING	19380	50/02
BO	Barbers Point - Oahu	21-09-00N 158-09-06W	REPORTED MISSING	19357	06/03
CC	Kaena Point - Lanai	20-51-00N 157-08-30W	REPORTED ADRIFT	19351	04/03
II	Haleiwa - Oahu	21-44-48N 158-13-18W	REPORTED MISSING	19357	03/03
JJ	Kamohio - Kahoolawe	20-24-12N 156-38-00W	REPORTED ADRIFT	19340	06/03
QQ	Makuu - Hawaii	19-39-12N 154-53-30W	REPORTED MISSING	19320	06/03

### DISCREPANCIES CORRECTED: Federal Aids:

LLNR	Name of Aid	Status	Chart Affected (Largest Scale)	BNM Reference	LNM Reference
28795	Heeia-Kea Small Boat Harbor Daybeacon	WATCHING PROPERLY	19359	052-03	04/03
28830	Sampan Channel Daybeacon 7	WATCHING PROPERLY	19359	051-03	04/03
30785	Apra Outer Harbor Light	WATCHING PROPERLY	81054		51/02

DISCREPANCIES CORRECTED: Private Aids: (None)

DISCREPANCIES CORRECTED: FAD Buoys: (None)

## III. TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED (None)

#### IV. CHART CORRECTIONS (C)

AD YR	Astronomic Datum (Year)	NAD YR	North American Datum (Year)
BABSAD	BAB South Astro Datum	OHD	Old Hawaiian Datum
LD	Local Datum	GUAM YR	Guam Datum (Togcha)
WGS YR	World Geodetic System (Year)		

Corrective action effecting charts is contained in this section. Chart Corrections are listed numerically by chart number beginning with the lowest and progressing through all charts affected. The correction listed pertains to that chart only. *It is up to the mariner to decide which charts are to be corrected.* The following example explains the individual elements of a typical correction.

Chart Number	Chart Edition	Edition Date	Last Local Notice to Mariners	Horizontal Datum Reference	Source of Correction	Current Local Notice to Mariners
19320	16Ed.	12/14/1996	LAST LNM 50/00	WGS 84	(CCGD 14)	24/02
	ISLAND OF HAWAII					
Change	Lt Characteristic to:	F G 38ft 10M		at	19-43-36.8 N	155-05-10.2 W
Corrective Action	Object of Corrective Action				Position (Degrees, minutes, seconds and tenths)	

A chart correction followed by:

**(Temp)** indicates that it is temporary in nature.

**P** indicates that it is preliminary, and that permanent corrective action will appear in a future Local Notice to Mariners.

The letter **M** immediately following the chart number indicates that the correction should be applied to the metric side of the chart only.

The letter **N** preceding the current Local Notice to Mariners number indicates that the affected chart is on Limited Distribution and is normally only for use by U.S. Navy, government-owned or government chartered vessels.

Courses and bearings are given in degrees clockwise from 000° T. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.

19353	12Ed.	04/15/2000	LAST LNM 25/00	WGS 84	(NOS NW -5893)	07/03
	HI – HARBORS OF MOLOKAI					
Substitute	20 ft. sounding to 9 ft sounding			at	21-04-43.2 N	157-01-49.1 W
19359	10Ed.	08/15/1999	LAST LNM 06/03	WGS 84	(CCGD 14)	07/03
	HI – OAHU – KANEOHE BAY					
Delete	Sampan Channel Buoy, R N “10”			at	21-26-55.5 N	157-47-39.6 W
Add	Sampan Channel Junction Buoy, GRG “S”			at	21-26-54.0 N	157-47-41.0 W

#### IV. NEW ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

LLNR	Name of Aid	Proposed Action	Charts Affected
28725	Kaneohe Bay Channel Daybeacon 7A	Rename to Kaneohe Bay Channel Daybeacon 9	19359
28735	Kaneohe Bay Channel Daybeacon 9	Rename to Kaneohe Bay Channel Daybeacon 11	19359
28730	Kaneohe Bay Channel Daybeacon 8	Rename to Kaneohe Bay Channel Daybeacon 12	19359
28740	Kaneohe Bay Channel Light 10	Rename to Kaneohe Bay Channel Light 14	19359
28745	Kaneohe Bay Channel Daybeacon 11	Rename to Kaneohe Bay Channel Daybeacon 15	19359
28750	Kaneohe Bay Channel Lighted Buoy 13	Rename to Kaneohe Bay Channel Lighted Buoy 17	19359
28755	Kaneohe Bay Channel Light 12	Rename to Kaneohe Bay Channel Light 18	19359
28760	Kaneohe Bay Channel Lighted Buoy 14	Rename to Kaneohe Bay Channel Lighted Buoy 20	19359
28765	Kaneohe Bay Channel Light 15	Rename to Kaneohe Bay Channel Light 21	19359
28775	Kaneohe Bay Channel Light 16	Rename to Kaneohe Bay Channel Light 22	19359
28780	Kaneohe Bay Channel Daybeacon 17	Rename to Kaneohe Bay Channel Daybeacon 23	19359
28785	Kaneohe Bay Channel Light 19	Rename to Kaneohe Bay Channel Light 25	19359
28790	Kaneohe Bay Channel Buoy 18	Rename to Kaneohe Bay Channel Buoy 26	19359
29670	Pokai Bay Breakwater Light 2	Discontinue.	19361
30710	Glass Breakwater Light	Increase nominal range from 5 to 6 NM.	81054, 81048
30725	Pier Dog Light	Increase nominal range from 5 to 6 NM.	81054

#### VI. NEW PROPOSED CHANGES IN AIDS TO NAVIGATION (None)

## VII. GENERAL

### MARINE EVENTS:

The following marine events are of interest to mariners. All mariners are cautioned that event areas warrant prudent seamanship and that all Federal, State and Local regulations apply.

**Sponsors and organizers frequently set up event areas prior to the actual activity. Additionally, post event clean-ups may be required. Mariners are urged to exercise caution in and around event areas prior to and after the published event times.**

Event and Location	Date	Activity	Sponsor
ILH SAILING PRACTICE Ala Wai Channel to Mamala Bay, Oahu	18-20 February 2003 4:00PM – 7:00PM	Sailboat Practice	Hawaii Yacht Club
MIL CANOE REGATTA Kahului Harbor, Maui	22 February 2003 7:00AM – 1:00PM	Canoe Race	Hawaiian Canoe Club
PAL/DOE/ILH/NOCRA REGATTA STATE CHAMPIONSHIP Keehi Lagoon ocean waters, Oahu	28-February-2003 6:00AM – 2 March 2003 5:00PM	Canoe Race	P.A.L./O.I.A./Na Opio Canoe Racing Association
RAFT RACE Waikiki ocean waters, Oahu	8 March 2003 10:00AM – 11:30AM	Raft Race	BGS Incentive Activities
JOE “STEW” KALAMA CANOE RACE Ala Wai Channel to Mamala Bay, Oahu	8 March 2003 7:00AM – 2:00PM	Canoe Race	South Shore Canoe Association

## VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI: PACIFIC COAST AND PACIFIC ISLANDS 2002

(1) Number	(2) Name and Location	(3) Position	(4) Characteristics	(5) Height	(6) Range	(7) Structure	(8) Remarks	LNM
28845	- Junction Buoy S	21 26 54 N 157 47 41 W				Green and red bands; can		07/03
	*	*				*		

## IX. ADDITIONAL ENCLOSURES (None)

END OF CCGD 14 LOCAL NOTICE TO MARINERS NO. 07/03.

R. D. UTLEY  
Rear Admiral, U. S. Coast Guard  
Commander, Fourteenth Coast Guard District